

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

IMPROVED SIGNAL PROCESSING APPARATUS AND METHOD

Diab et al.

Appl. No.: Unknown

Atty Docket: MASIMO.56DC1C1




FIG. 1




FIG. 2A




FIG. 2B




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9

IMPROVED SIGNAL PROCESSING APPARATUS AND METHOD

Diab et al.

Appl. No.: Unknown

Atty Docket: MASIMO.56DC1C1





FIG. 10



FREQUENCY

FIG. 11




FIG. 12








FIG. 13





AM EFFECTS

FIG. 15




FIG. 16A




FIG. 16B




FIG. 16C

IMPROVED SIGNAL PROCESSING APPARATUS AND METHOD

Diab et al.

Appl. No.: Unknown

Atty Docket: MASIMO.56DC1C1





FIG. 17






FIG. 18B




FIG. 18C




FIG. 19